

**ARAB REPUBLIC OF EGYPT  
MINISTRY OF TRANSPORT  
EGYPTIAN AUTHORITY FOR MARITIME SAFETY**

**Notice to Mariners No. (4)/2025**

**Suez Canal :**

For shipmasters, shipping companies, and their agents, kindly be notified that the following data were deleted from to the Affected charts, in order to ensure the safety of maritime navigation in the region :

● **(Special Purpose) in position:**

No.	Lat		Long	
1	31° 15'.929	N	032° 19'.130	E
2	31° 15'.538	N	032° 18'.838	E
3	31° 15'.337	N	032° 18'.709	E
4	31° 14'.940	N	032° 18'.402	E

● **( Mooring Buoy) in position:**

No.	Lat		Long	
1	31° 15'.876	N	032° 19'.473	E
2	31° 15'.880	N	032° 19'.090	E
3	31° 15'.767	N	032° 19'.005	E
4	31° 15'.698	N	032° 18'.954	E
5	31° 15'.583	N	032° 18'.867	E
6	31° 15'.312	N	032° 18'.677	E
7	31° 15'.207	N	032° 18'.593	E
8	31° 15'.097	N	032° 18'.514	E
9	31° 14'.974	N	032° 18'.425	E
10	31° 15'.450	N	032° 18'.615	E
11	31° 15'.325	N	032° 18'.512	E

• **(Anchor Berths) in position:**

No.	Lat			Long		
1	31°	15'.907	N	032°	19'.426	E
2	31°	15'.823	N	032°	19'.047	E
3	31°	15'.735	N	032°	18'.983	E
4	31°	15'.648	N	032°	18'.915	E
5	31°	15'.250	N	032°	18'.625	E
6	31°	15'.171	N	032°	18'.564	E
7	31°	15'.050	N	032°	18'.481	E
8	31°	15'.404	N	032°	18'.571	E

- ❖ All ships should take into account safety sailing precautions, and all seafarers should apply.
- ❖ Affected Charts Number : SC01 INT (7156) PANEL (A) PORT SAID TO EL TINA  
M22 INT (3549) PANEL (A) PORT SAID HARBOUR,
- ❖ Alexandria : 20/2/2025.